

Enriching lives through innovation



chemical-concepts.com 800.220.1966

410 Pike Road • Huntingdon Valley, PA 19006

Advanced Materials

ARALDITE[®] 8579 Resin Hardener 8579

HEAT- AND CHEMICAL-RESISTANT EPOXY ADHESIVE

GENERAL

ARALDITE 8579 Resin/Hardener 8579 epoxy adhesive is a solvent-free. thixotropic, cold-setting paste that spreads easily and has good gap-filling characteristics. The cured system is chemical resistant and has good mechanical strength up to 248°F (120°C).

NOTE: This product is the equivalent of ARALDITE AV 138M resin/Hardener HV 998 epoxy adhesive.

FEATURES

Easy to mix and apply

Gap-filling

No-pressure curing

Cures with negligible shrinkage and without releasing volatiles

Good high-temperature performance

ADVANTAGES

Good resistance to static and dynamic loading

Good resistance to chemicals and tropical weathering

Electrically insulating

TYPICAL PROPERTIES

Property Color/appearance Specific Gravity Viscosity, cP @ 77°F

(25°C)

Test Values⁽¹⁾

Hardener **Test Method** Resin Visual Pale Beige Gray ASTM D-792 1.71 1.68 **ASTM D-2393** 60,000 500,000

TYPICAL MIXED **PROPERTIES**

Property Reaction Ratio (by weight)

Test Method

Test Values (1) 100R/40H

100R/40H

Pot Life, minutes @ 77°F ASTM D-2471 (25°C), 100 gram mass

Reaction Ratio (by volume)

Mixed viscosity, cP

60

@ 77°F (25°C)

ASTM D-2393

125.000

¹Tested @ 77°F (25°C)



RECOMMENDED CURE SCHEDULES

Temperature
41°F (5°C)
50°F (10°C)
73°F (23°C)
104°F (40°C)
176°F (80°C)
212°F (100°C)

Minimum Cure Time

3 days
24 hours
8 hours
2 hours
15 minutes
15 minutes

PROCESSING

Application of Adhesive

The resin/hardener mix is applied with a spatula to the pretreated and dry joint surfaces.

A layer of adhesive 0.002 to 0.004-inches (0.05 to 0.10-mm) thick will normally impart the greatest lap shear strength to a joint.

The joint components should be assembled and clamped as soon as the adhesive has been applied. Even contact throughout suffices to ensure proper cure.

Standard Test Specimens

Unless otherwise stated, the figures given below were all determined by testing standard specimens made up by lap-jointing 4-inch x 1-inch x 0.06-inch (10-cm x 2.5-cm x 1.5-mm) strips of aluminum. The joint area was 0.5×1 inch (12.5 mm x 2.5 cm) in each case.



TYPICAL PHYSICAL PROPERTIES

Test Method

Lap Shear Strength, psi (MPa)

ASTM D-1002

Effect of Cure Time and Test Temperature

<u>Cure</u>	<u>Time</u>	<u>Test Values⁽¹⁾</u>
Temperature		
41°F(5°C)	4 days	1700(11.7)
59°F(15°C)	24 hours	1900(13.1)
77°F (25°C)	24 hours	2300(15.8)
104°F(40°C)	16 hours	2500(17.2)
176°F(80°C)	15 minutes	2900 (20)
212°F(100°C)	10 minutes	3000 (20.6)

¹Tested @ 77°F (25°C)

Lap Shear Strength, psi (MPa) Effects of Test Temperature

Load applied 10 minutes after specimens reach test temperature.

Cure Cycle	Test Temp.	<u>Test Values⁽¹⁾</u>
48 hours at 77°F (25°C)	-4°F (-20°C)	2100(14.5)
	68°F (20°C)	2300(15.8)
	104°F (40°C)	2500(17.2)
	140°F (60°C)	2700(18.6)
	212°F(100°C)	1900(13.1)
	248°F (120°C)	1200(8.3)

¹Tested @ 77°F (25°C)

Test Method ASTM D-1002

Lap Shear Strength, psi (MPa)

Effect of Immersion

Cure cycle 48 hours @ 77°F (25°C). Immersion for 90 days in media listed.

<u>Properties</u>	Test Values (1)
Standard - As prepared	2500(17.2)
Acetone (30 days)	2300(15.8)
Gasoline	2350(16.2)
Ethyl Acetate (30 days)	2800(19.3)
Acetic Acid 10%	2000(13.8)
Methanol	2500(17.2)
Lubricating Oil - HD30	2500(17.2)
Kerosene	2600(17.9)
Trichloroethylene	2400(16.5)
Water @ 68°F (20°C)	2700(18.6)
Water @ 194°F (90°C)	2600(17.9)

Lap Shear Strength, psi (MPa) *Effect of Tropical Exposure*

(104°F/40°C/92% R.H.)

Cure Cycle	Exposure Time	Test Values (1)
48 hours @ 77°F (25°C)	0 days	2500(17.2)
	30 days	3000 (20.6)



Lap Shear Strength, psi (MPa) Effect of Heat Aging

Cured 16 hours @ 77°F (25°C).

Aging Temperature	Exposure Time	Test Values
77°F (25°C)	Standard-as	2500(17.2)
	prepared	
	1 year	2700(18.6)
176°F (80°C)	90 days	2700(18.6)
	1 year	2700(18.6)
212°F(100°C)	90 days	2700(18.6)
302°F(150°C)	90 days	2500(17.2)

Lap Shear Strength, psi (MPa) Tested on Metal Substrates (Cured 20 min @ 77°F (25°C)

<u>Metal</u>	<u>Substrate</u>	<u>Test</u>
	Thickness (in./mm)	<u>Values</u>
Carbon Steel	1.0 (25 mm)	3000 (20.6)
Stainless Steel	1.0 (25 mm)	2700(18.6)
Galvanized Steel	1.5 (40 mm)	2700(18.6)
Copper	1.5 (40 mm)	2700(18.6)

Test Method ASTM D-1002

Fatigue Strength

Fatigue Limit Load,	Cycles to Failure
% Static Shear Strength	
40	10 ⁵ 10 ⁶
30	10 ⁵ 10 ⁶
25	>10 ⁷

These physical properties are reported as typical test values obtained by our test laboratory. If assistance is needed in establishing product specifications, please consult with the Huntsman Quality Control Department.



STORAGE AND SHELF LIFE

ARALDITE epoxy adhesive components should be stored in their original, sealed containers at room temperature. When stored at temperatures from 59-77°F (15-25°C), the resin and hardener will remain in useable condition for 3 years from date of shipping from Huntsman.

SAFETY/HANDLING PRECAUTIONS

Do not use or handle this product until the Material Safety Data Sheet has been read and understood

Personal Hygiene

Safety precautions at workplace

Protective clothing Yes
Gloves Essential

Arm protectors Recommended when skin contact

is likely

Goggles/safety glasses Yes

Skin protection

Before starting work Apply barrier cream to exposed skin
After washing Apply barrier or nourishing cream

Cleansing of contaminated skin Dab off with absorbent paper, wash

with warm water and alkali-free soap, then dry with disposable towels.

Do not use solvents.

Clean shop requirements Cover workbenches/areas with light

colored paper. Use disposable

beakers.

Disposal of spillage Soak up with sawdust or cotton waste

cloth and deposit in plastic-lined bin.

Ventilation

Of workshop Renew air 3 to 5 times an hour Of workplaces Exhaust fans should be used to

prevent operators from inhaling

vapors.



FIRST AID

Contamination of the *eyes* by resin, hardener or mix should be treated immediately by flushing with clean, running water for 10 to 15 minutes. A doctor should then be consulted.

Material smeared or splashed on the *skin* should be dabbed off, and the contaminated area then washed and treated with a cleansing cream (see above). A doctor should be consulted in the event of severe irritation or burns. Contaminated clothing should be changed immediately.

Anyone taken ill after inhaling vapors should be moved out of doors immediately.

In all cases of doubt call for medical assistance.

CAUTION:

Huntsman Advanced Materials Americas Inc. maintains up—to-date Material Safety Data Sheets (MSDS) on all of its products. These sheets contain pertinent information that you may need to protect your employees and customers against any known health or safety hazards associated with our products. Users should review the latest MSDS to determine possible health hazards and appropriate precautions to implement <u>prior to</u> using this material. Copies of the latest MSDS may be requested by calling our customer service group at 888-564-9318 or emailing your request to <u>adhesives@huntsman.com</u>.

KEEP OUT OF REACH OF CHILDREN
FOR PROFESSIONAL AND INDUSTRIAL USE ONLY



IMPORTANT LEGAL NOTICE

Sales of the product described herein ("Product") are subject to the general terms and conditions of sale of either Huntsman Advanced Materials LLC, or its appropriate affiliate including without limitation Huntsman Advanced Materials (Europe) BVBA, Huntsman Advanced Materials Americas Inc., or Huntsman Advanced Materials (Hong Kong) Ltd. ("Huntsman"). The following supercedes Buyer's documents.

Huntsman warrants that at the time and place of delivery all Products sold to Buyer shall conform to the specifications provided to Buyer by Huntsman.

While the information and recommendations included in this publication are, to the best of Huntsman's knowledge, accurate as of the date of publication, NOTHING CONTAINED HEREIN (EXCEPT AS SET FORTH ABOVE REGARDING CONFORMANCE WITH SPECIFICATIONS PROVIDED TO BUYER BY HUNTSMAN) IS TO BE CONSTRUED AS A REPRESENTATION OR WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, NONINFRINGEMENT OF ANY INTELLECTUAL PROPERTY RIGHTS, OR WARRANTIES AS TO QUALITY OR CORRESPONDENCE WITH PRIOR DESCRIPTION OR SAMPLE, AND THE BUYER ASSUMES ALL RISK AND LIABILITY WHATSOEVER RESULTING FROM THE USE OF SUCH PRODUCT, WHETHER USED SINGLY OR IN COMBINATION WITH OTHER SUBSTANCES.

No statements or recommendations made herein are to be construed as a representation about the suitability of any Product for the particular application of Buyer or user or as an inducement to infringe any patent or other intellectual property right. Buyer is responsible to determine the applicability of such information and recommendations and the suitability of any Product for its own particular purpose, and to ensure that its intended use of the Product does not infringe any intellectual property rights.

The Product may be or become hazardous. The Buyer should obtain Material Safety Data Sheets and Technical Data Sheets from Huntsman containing detailed information on Product hazards and toxicity, together with proper shipping, handling and storage procedures for the Product, and should comply with all applicable governmental laws, regulations and standards relating to the handling, use, storage, distribution and disposal of, and exposure to the Product. Buyer shall also take all steps necessary to adequately inform, warn and familiarize its employees, agents, direct and indirect customers and contractors who may handle or be exposed to the Product of all hazards pertaining to and proper procedures for safe handling, use, storage, transportation and disposal of and exposure to the Product, and the containers or equipment in which the Product may be handled, shipped or stored.

Araldite and Aradur are registered trademarks of Huntsman Corporation or an affiliate thereof in one or more, but not all countries.

© 2007 Huntsman Advanced Materials Americas Inc.

Main Offices:
Huntsman Corporation
10003 Woodloch Forest Dr.
The Woodlands
Texas 77380
(281) 719-6000

Huntsman Advanced Technology Center 8600 Gosling Rd. The Woodlands Texas 77381 (281) 719-7400

